


Light Fastness Rate P.A 6.6



Shade	BL0320	RE0001	YE0300	BK0003	NA0062	BL0787	BL0159	GR0033	PU0212	PU0387
Xenon Lamp Rate	6	6	6	6	4	3	6	6	6	6

Shade	PU0066	PI0573	PI0149	OR0282	OR0077	OR0441	YE0029	YE0077	GN0033	GN0913
Xenon Lamp Rate	6	5	2	4	3	6	6	3	3	6

EN: UV Table Light Fastness rate: 5-6 very good, 5 good, 4 medium, 3 low and 2 very low

POR: Tabela UV – Resistencia da cor à descoloração: 5-6 muito bom (perde pouca cor), 5 bom, 4 media, 3 baixa e 2 muito baixa