



Harness inspection certificate

Inspection certificate number: **PH_255.2018**

Impact pad number: **n/a**

Manufacturer data

Manufacturer name: **Sol Paragliders - Sol Sports Ltda.**
 Representative: **Ary Carols Pradi**
 Street: **Rua Walter Marquardt,1180**
 Post code / place: **Cep 89259-700 Jaragua do Sul, SC**
 Country: **Brazil**

Sample data:

Harness

Impact pad

Name:	Alpamayo	Name Impact pad: ⁽¹⁾	n/a
Type:	ABS	Impact pad integrated: ⁽¹⁾	n/a
Size:	unique size	Impact pad type:	n/a
Weight of Sample [kg]:	0.463	Weight of Sample [kg]: ⁽¹⁾	n/a
Serial number:	23469	Serial number: ⁽¹⁾	n/a
Clip-in weight [kg]:	100		
Integrated container for rescue system:	n/a	Date of reception:	n/a
Volume container [cm ³]:			
		n/a max	
		n/a min	
Date of reception:	21.02.2018		


Test report summary

Structural test

Impact pad test

Result	POSITIVE	n/a
Place	Villeneuve	Villeneuve
Date	24.02.32018	n/a

Issue data

Place of declaration: **Villeneuve**
 Date of issue: **13.12.2018**
 Managing Director: **Alain Zoller**
 Signature: 

This signature approve the validity of the test reports if available; no. 94.21 (test id R0,R2,R6,R8,R9,R10,RRDT,RRST) and no. 94.22 (test id: P1,P2,PR1,PR2)
Air Turquoise SA, having thoroughly assessed the sample mentioned above, declare it was found conform with all requirements defined by the following norms:

European Standard **EN1651 :1999**, and **EN12491:2015 chapter 5.3.2**

⁽¹⁾ If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismounted from the harness, e.g. airbag.

Present declaration's scope only extends to the conformity of a given sample, on a given date and in a given place – as mentioned here above.

This inspection certificate contain the following test and is complet with the test, if available, report: 94.21 and 94.22