AIR TURQUOISE SA | PARA-TEST.COM Route du Pré-au-Comte 8 * CH-1844 Villeneuve * +41 (0)21 965 65 65

Test laboratory for paragliders, paraglider harnesses and paraglider reserve parachutes



Harness inspection certificate

Brazil

Inspection certificate number:	PH_237.2018	Impact pad number:	PH_237.2018
Manufacturer data			
Manufacturer name:	Sol Paragliders - Sol Sports Ltd	a.	
Representative:	Ary Carols Pradi		
Street:	Rua Walter Marquardt,1180		

Cep 89259-700 Jaragua do Sul, SC

Sample data:	Harness			Impact pad
Name:	AMX 2		Name Impact pad: (1)	n/a
Туре:	ABS		Impact pad integrated: (1)	Yes
Size:	L		Impact pad type:	Foam
Weight of Sample [kg]:	4.8		Weight of Sample [kg]: (1)	n/a
Serial number:	23491		Serial number: ⁽¹⁾	n/a
Clip-in weight [kg]:	120			
Integrated container for rescue system:	Yes		Date of reception:	12.04.2018
Volume container N° 1 [cm ³]:		6000 max		
		3000 min		
Volume container N° 2 [cm ³]:		4000 max		
		2500 min		
Date of reception:	12.04.2018			

Test report summary	Structual test	Impact pad test	
Result	POSITIVE	POSITIVE	
Place	Villeneuve	Villeneuve	
Date	04.06.2018	16.04.2018	
Date	04.06.2018	16.04.2018	

Issue data

Post code / place:

Country:

Place of declaration: Date of issue: Managing Director: Signature: Villeneuve 28.06.2018 Alain Zoller

A

This signature approve the validity of the test reports if available; no. 94.21 (test id R0,R2,R6,R8,R9,R10,RRDT,RRST) and no. 94.22 (test id: P1,P2,PR1,PR2) Air Turquoise SA, having thoroughly assessed the sample mentioned above, declare it was found conform with all requirements defined by the following norms: European Standard EN1651 :1999, and EN12491:2015 chapter 5.3.2 - Airworthiness Requirements LTF NfL II 91/09 chapter 4.2.1, 5, 6.1.5 and 6.1.8

(1) If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismounted from the harness, e.g. airbag.

Present declaration's scope only extends to the conformity of a given sample, on a given date and in a given place – as mentioned here above.

This inspection certificate contain the following test and is complet with the test, if available, report: 94.21 and 94.22